

APPLICATION – SAFETY & HANDLING

- Protective eyewear and gloves are recommended when handling or applying
- Do not apply the coating in hot, direct sunlight or if glass surface temperature is in excess of 32°C or below 0°C.
- Do not apply on wet, rainy days or when the humidity is above 90%

SPRAY OR WIPE ON APPLICATION INSTRUCTIONS:

- Spray product directly and evenly onto clean glass surface using a fine mist sprayer
- Hold sprayer approximately 12-20cm from glass - closer may cause product runoff
- Make sure the glass is visibly wet with product
- After spraying a fine mist use microfiber stick or clean cloth to spread product evenly

15-20CM AWAY FROM GLASS



SPREAD EVENLY



- Cloth or microfiber stick can be continually reused for application. Must remain clean & uncontaminated by soil or other chemicals including water.
- Allow the product to dry on the glass (2-3 min.) Or until evaporated
- Allow the coating to dry until a slight haze
- Re-apply a 2nd coating to ensure complete coverage if necessary
- Remove any excess haze by spraying or rinsing the glass with clean water
- Dry with cotton/microfiber or paper towel (tool) until crystal clear

QUALITY CONTROL:

- To test glass for water repellency, spray mist of water. You will see small round water drops with a contact angle above 108°
- Storage & Shelf life - **Invisible Shield** Glass Coating contains a flammable solvent and should not be used or stored near an open flame or at temperatures above or 45°C. Store away from direct sunlight, in a cool dry place. Shelf life of **Invisible Shield** is indefinite in closed containers.

POISON CONTROL - CHEMTEL: 1-800-255-3924